



HAND TIGHTEN ONLY DO NOT OVER TIGHTEN ON POWER DRILL

FINISHED



C	Ø16xØ6xL. 2			4
B	M6x40			4
A	4mm			1
NO.		DIAGRAM		QTY

1. As shown in Diagram place chair upside down on soft clean surface.
2. Line up chair base as shown; ensure frame form a Z and all 4 holes line up.
3. By hand take bolt (B) with washer (C) insert thru hole in chair base into threaded hole, turn 2-3 turns by hand, repeat till all 4 bolts are seated correctly, with allen key (A) tighten all bolts till firm.
4. Do not over tighten.
5. Ready for use

PU CARE AND MAINTENANCE

Do NOT use detergents, solvents abrasives, non-recommended PU cleaners. Do NOT dry clean or machine wash. Protect from direct sunlight and heat sources, both direct and through heating vents.

Vacuum regularly with the soft brush attachment of the vacuum cleaner to remove dust and grt, then wipe with a soft, colourfast cloth dampened with plain water. This should be done as often as necessary or at least every 2-3 weeks.

When cleaning PU do not rub excessively or too hard. Always let the product do the work and adhere to the manufacturer's instructions. Use only a soft, colour fast or white cloth sponge.

PU CARE AND MAINTENANCE CONTINUED

Special note - The salts and body oils, which occur naturally in human skin, can damage the surface of the PU if left unclean for lengthy periods. In warm or humid weather it is important that PU be wiped over weekly, particularly if the PU has become damp with perspiration or deposits of body oils are visible on areas such as head rests or arm rests and other areas of the furniture that comes in contact with the body.

Always clean along any creases that have developed in the PU and pay particular attention to areas that are come in contact with the skin.

Deterioration due to incorrect or inadequate maintenance including deterioration caused by body oils, hair spray, gel mousse, perfume, deodorants, medication and dye penetration from clothes, cannot be considered a fault in the PU and claims due to this will not be considered.

METAL FINISH MAINTENANCE

Finish is polished steel to ensure lustre please dust with a soft clean cloth regularly. In areas of high salt & humidity/ please clean every 2-3weeks. Do not use solvents or abrasive cleaners, may use damp cloth to clean off spills of liquid, ensure liquid spills clean off immediately.

*** PLEASE REFER TO YOUR WARRANTY SWING TAG FOR FURTHER MAINTENANCE REQUIREMENTS.**

Made In China

Imported By Furniture Solutions (Aust) Pty Ltd