

Helpful hints to make assembly stress free. Ensure surface area you are working with is level, clean & has soft surface.
Contact Furniture Solutions if any parts are missing: Email customerservice@furnitureolutions.com.au PH: 1300 794 188 (Aust)




Parts










NO.	PICTURE	QTY
③		4
④		4
⑤		4
⑥		4
⑦		8
⑧		4
⑨		4
⑩		1
⑪		1

Components




NO.	PICTURE	QTY
①		1
②		4
*		1



Parts

NO.	PICTURE	QTY
③		4
④		4
⑤		4
⑥		4
⑦		8
⑧		4
⑨		4
⑩		1
⑪		1

Components

NO.	PICTURE	QTY
①		1
②		4
*		1



Helpful hints to make assembly stress free. Ensure surface area you are working with is level, clean & has soft surface.
Contact Furniture Solutions if any parts are missing: Email customerservice@furnitureolutions.com.au PH: 1 300 794 188 (Aust)

